



Montgomery County Land Bank
130 West Second Street, Suite 1425
Dayton, OH 45402

THE DIY RENOVATION PROGRAM IS BACK IN BUSINESS!

The Montgomery County Land Bank is pleased to announce we resumed offering houses for sale in our DIY Renovation Program beginning May 7, 2020. As you might expect, some procedures will have changed. Keeping the safety of our customers and staff foremost in our minds please be aware of the following:

The Land Bank staff will continue working remotely for the foreseeable future.

Property Viewing

- ❖ Interior inspections of DIY properties will not be offered. However, there will be plenty of photographs including detailed pictures of the areas requiring renovations in the Pre-Sale Inspection Report.
- ❖ **You may also view a video of the property at:** <https://youtu.be/iXCZlnzgvyg>
- ❖ If your offer is accepted, you will have the opportunity to inspect the interior of the property. You will have 3 days from your interior inspection to rescind or move forward with the purchase of the property.
- ❖ You are strongly encouraged to inspect the exterior of the property. Please maintain social distance if another interested party is there at the same time.

Submitting Offers

- ❖ Please do not come into the office to submit your offer. Land Bank offices are still closed to the public.
- ❖ Submit your offer via email if at all possible.
- ❖ Offers submitted by mail will also be accepted.

Contract Signing

- ❖ Contact signing will also be handled electronically.
- ❖ Purchasers will receive instructions on how to pay for the property, sign the contract and get possession of the property.

It's a new world for all of us. We appreciate you sticking with us and your patience while we adjust to these extraordinary circumstances.

Thank you,

Susan Considine
Program Manager

sconsidine@mclandbank.com

Sue Pratt

Assistant Program Manager

spratt@mclandbank.com

Montgomery County Land Bank

130 West 2nd Street, Suite 1425

Dayton, OH 45402

Address: 969 Manhattan Avenue

City: Dayton, OH 45406

Inspector: Sue Pratt

Pre-Sale Number: _____

Location: _____

Phone Number: _____

PRE • SALE INSPECTION REPORT

On 6/24/2020 a Pre-Sale inspection was performed by Sue Pratt at the above location. The deficiencies listed in this inspection report must be complied before Deed will be transferred. Review all deficiencies Marked (X) in the inspection report and make proper corrections before scheduling a re-inspection. Re-inspections can be scheduled by calling 937-531-7053 between the hours of 8:30 a.m. - 4:30p.m. Monday-Friday.

This inspection report is valid for six (6) months from the date of initial inspection.

This inspection report covers only those items listed on the inspection report. The inspector is not required to activate the heating system, use a ladder to observe the condition of the roof, evaluate inaccessible or concealed areas or disassemble items. This report does not address formaldehyde, lead based paint, any air born gases {including radon}, asbestos, wood stoves, termite infestation, or air conditioners.

NOTE:

1. Passing inspection, i.e. not marked (X) is NOT a WARRANTY or GUARANTY.
2. THERE WERE NO UTILITIES ON AT THE TIME OF INSPECTION.

This report is intended to be used as a tool by potential purchasers. Contained herein are the conditions the inspector has observed that may impact decisions potential buyers make regarding this property. The Land Bank requires the deficiencies described in this report be remedied but will not dictate the method of resolution. The goal is that renovations result in a Warm, Dry, Safe, Clean structure.

FINAL CLEAN

Remove from site all construction materials, tools, and debris. Sweep clean all exterior work areas. Vacuum all interior work areas, removing all visible dust, stains, labels, and tags. Clean all windows.

BUILDING CODE REQUIRES PERMITS AND INSPECTIONS ON MOST HVAC, PLUMBING AND ELECTRICAL INSTALLATIONS. IT IS THE PURCHASER'S RESPONSIBILITY TO OBTAIN THE REQUIRED PERMITS AND INSPECTIONS ON ANY WORK. EXPECT THE LAND BANK TO ASK FOR PROOF OF PERMITS AND INSPECTIONS AT THE FINAL WALK THROUGH. DEED CANNOT BE TRANSFERRED WITHOUT APPROPRIATE DOCUMENTATION. NOTE: YOU WILL NEED TO CHOOSE A CONTRACTOR REGISTERED WITH THE CITY OF DAYTON TO PULL PERMITS. THE CITY OF DAYTON DOES NOT CONSIDER YOU THE OWNER OF THE PROPERTY, SO YOU WILL NOT BE ABLE TO PULL PERMITS IN YOUR NAME.

PRE • SALE INSPECTION REPORT

Location: 969 Manhattan Inspector: Sue Pratt Date: 6/24/2020

EXTERIOR: STRUCTURAL

[EXT]: DWELLING

[EXT. S1] (X) Replace the roof complete. STRIP THE ROOF TO THE SHEATHING. INSTALL 7/16" O.S.B. SHEATHING TO THE ENTIRE ROOF STRUCTURE. INSTALL NEW ROOFING TO CONFORM TO CURRENT CODE. FLASH THE BRICK CHIMNEY. INSURE THERE IS FLASHING/COUNTERFLASHING AT THE DORMERS. NOTE THE BACK PORCH ROOF/WALK OUT FROM SECOND LEVEL.

[EXT. S2] (X) Repair/replace defective or missing gutters and downspouts so water will properly drain away from dwelling foundation (X) front (X) side (X) rear.

REPLACE ALL THE GUTTERS AND DOWNSPOUTS. INSTALL SPLASH BLOCKS OR EXTENSIONS TO INSURE WATER DRAINS AWAY FROM THE HOUSE.

[EXT. S3] (X) Repair/replace defective or missing: (X) door casing/jambs (X) siding/exterior trim: (X) front (X) side (X) rear. REPLACE MISSING/DAMAGED SIDING, MATCH EXISTING AS CLOSE AS POSSIBLE. REPLACE ANY DAMAGED FASCIA/SOFFIT/RAKE.

[EXT. S4] (X) Repair window sash, (X) replace broken glass and putty windows: (X) front (X) side (X) rear. INCLUDES BASEMENT WINDOWS. NOTE: THERE CAN BE NO PEELING PAINT OR PAINT CHIPS LEFT AT THE PROPERTY.

[EXT. S5] (X) Repair cracks and open joints: () masonry steps (X) porch walls () columns (X) chimney (X) dwelling walls: (X) front (X) side (X) rear.

[EXT. S6] (X) Repair/replace defective porch components: (X) joists (X) rails (X) columns (X) skirting (X) decking (X) ceiling (X) risers (X) steps (X) stringers: () front () side (X) rear. IN ADDITON CONSIDER WHAT KIND OF REPAIR WILL BE NECESSARY FOR THE PORCH ROOF TO ACCOMMODATE THE WALK OUT FROM THE SECOND LEVEL.

[EXT. S7] () Remove: () junk () debris () rubbish from exterior to eliminate unsanitary condition.

[EXT. S8] (X) Repair or replace defective/missing locks and hardware on doors and windows of dwelling: (X) front (X) side (X) rear.

INSURE ALL WINDOWS AND DOORS ARE OPERABLE AND LOCKABLE

[EXT. S9] (X) Remove all peeling paint and re-paint and or re-stain with an approved material.

APPLIES TO ALL PREVIOUSLY PAINTED EXTERIOR HOUSE COMPONENTS. THERE CAN BE NO PEELING PAINT OR PAINT CHIPS LEFT AT THE PROPERTY.

[G/S]: GARAGE/SHED

[G/S. 1] () Repair / replace defective or missing roof.

[G/S. 2] () Repair defective: () siding () doors () vehicle doors () cracked floor () rafters () sill plates, () roof boards.

[G/S. 3] () Prep peeling paint and re-paint with an approved material.

[G/S. 4] () Straighten and brace out of plumb walls.

[G/S. 5] () Repair window sash () replace broken glass and putty windows: () front () side () rear.

[G/S. 6] () Repair/replace: () electrical receptacles () light fixtures () wall switches () receptacle covers.

[G/S. 7] () Repair or replace defective or missing locks and hardware on doors and windows.

[G/S. 8] () Remove dilapidated structure.

OTHER DEFICIENCIES:

(X) REPLACE THE MAILBOX

(X) LEAVE THE YARD IN A WELL TENDED AND LANDSCAPED CONDITION/ FINISHED YARD CONDITION TO CONFORM TO SITE CONDITIONS AS LISTED IN THE LAND BANK REFERENCE GUIDE FOR CONSTRUCTION QUALITY STANDARDS. ONE LANDSCAPED BED IN THE FRONT YARD IS THE MINIMUM IMPROVEMENT EXPECTED. INCLUDE EDGING THE SIDEWALK AND THE CURB AT THE STREET, AND CLEARING ANY ORGANIC MATTER FROM THE ENTIRE YARDWALK, FROM FRONT PORCH TO THE ALLEY.

PRE - SALE INSPECTION REPORT

Location: 969 Manhattan Inspector: Sue Pratt Date: 6/24/2020

INTERIOR; STRUCTURAL

[INT.] DWELLING

[INT. S1] (X) Repair /replace defective /missing: (X)door (X)door hardware () sills (X) casings (X)jamb:

ALL CLOSETS AND INTERIOR ROOMS TO HAVE OPERABLE DOORS. ALL BY-PASS DOORS TO HAVE FLOOR DOOR GUIDES

[[INT. S2] (X) Repair /replace defective or missing: (X) treads (X) stringers (X) risers (X) hand /guard rails on stairs: (X) basement () first floor (X)second floor (X) third floor.

IN ADDITION: INSURE ALL STAIRCASES HAVE HANDRAILS. CLOSE IN THE ATTIC HAND RAIL TO ELIMINATE ANY GAPS LARGER THAN 4"

[INT. S3] (X) Repair/replace defective missing: (X) floor covering _____ (X) ceiling _____

ALL FLOORS AND CEILINGS THROUGHOUT TO HAVE A SAFE/SOUND/SANITARY PERMANENT SURFACE. IF EXISTING HARDWOOD FLOORS ARE TO BE RETAINED, FLOORS MUST BE SANDED AND FINISHED WITH A SEALER.

[INT. S4] (X) Repair / replace defective/ missing: (X) floor () floor joists () support beams () columns

[INT. S5] (X) Repair defective /leaking basement foundation walls: () front () rear () side. (X) NOTE THE CURRENT CONDITION OF THE BASEMENT WALLS. IT IS EXPECTED THAT THE INSTALLATION OF GUTTERS AND DOWNSPOUTS WILL HELP ALEVIATE SOME OF THE BASEMENT MOISTURE.

[INT.S6] (X) Repair /replace defective /missing: (X) plaster () drywal () other _____

REPAIR THROUGHOUT AS NECESSARY.

[INT. S7] (X) Remove all peeling paint and re-paint with an approved material:

PREP/PRIME/PAINT ALL PREVIOUSLY PAINTED SURFACES. FULL COVER NO SHOW THROUGH

[INT. S8] () Remove () junk () debris () rubbish to eliminate unsanitary condition.

[S.D.]SMOKE ANDCARBON MONOXIDE DETECTORS

[S.D.1] (X) Provide smoke detectors at the top of each stairwell leading to: (X) first floor (X) second floor (X) third floor.

[S.D.2] () Provide smoke detector on each level of the home.

[S.D.3] () Provide smoke detectors within or immediately outside of a doorway leading to a room used for sleeping: () first floor () second floor () third floor..

[S.D.4] (X) Provide a smoke detector in each bedroom.

[S.D.5] (X) Carbon monoxide detectors shall be located, installed/mounted as required by local code. In the absence of local code, carbon monoxide detectors shall be located **on each level of the home**, installed per the manufacturer's specifications

[ERG.] = EGRESS

[ERG.1] (X) Maintain at least one (1) window in each bedroom unrestricted as a means of egress for fire safety.

ERG.2] (X) Maintain at least one (1) means of egress without the use of an interior keyed lock.

OTHER DEFICIENCIES:

(X) INSURE KITCHEN CABINETS ARE SAFE/SOUND/AND SANITARY. REPAIR OR REPLACE AS NECESSARY. REPLACE THE KITCHEN COUNTERTOPS

(X) THE FIREPLACE IS ASSUMED TO BE INOPERABLE

(X) REPLACE BATHROOM WINDOWS WITH A TEMPERED GLASS WINDOW OR ELIMINATE THE WINDOW.

[BLDG. 1] () SECURE BUILDING PERMIT FOR: _____

PRE - SALE INSPECTION REPORT

Location: 969 Manhattan Avenue Inspector: Sue Pratt Date: 6/24/2020

INTERIOR: ELECTRICAL

[INT. E] ELECTRICAL

[INT. E1] (X) Repair/replace defective / missing wall switches: (X) living room (X) dining room (X) attic (X) kitchen, (X) exterior (X) basement () utility room (X) bedrooms (X) bathrooms () garage

[INT. E2] (X) Repair /replace defective /missing light fixtures: (X) living room (X) dining room (X) attic (X) kitchen (X) exterior (X) basement () utility room (X) bedrooms (X) bathrooms () garage

[INT. E3] (X) Repair / replace defective / missing plug outlets: (X) living room (X) dining room (X) attic (X) kitchen (X) exterior (X) basement () utility room (X) bedrooms (X) bathrooms () garage

[INT. E4] (X) Replace missing: (X) receptacle covers (X) switch covers: (X) living room (X) dining room (X) attic (X) kitchen (X) exterior (X) basement () utility room (X) bedrooms (X) bathrooms () garage

[INT. E5] () Install Type S fuses / circuit breakers of correct ampere rating to protect electrical wiring.

[INT. E6] (X) Remove or replace unapproved wiring : () living room () dining room () attic () kitchen () exterior () basement () utility room () bedrooms () bathroom () garage

REPLACE ANY UNAPPROVED WIRING THROUGHOUT THE PROPERTY

[INT. E7] (X) Replace existing electric service with new approved 100 - ampere service.

(X) Replace defective / missing service entrance conductors. NEW PANEL TO BE A MINIMUM OF 20 CIRCUITS.

[INT. E8] (X) Install required number of electrical receptacles. The new receptacles shall be duplex grounding type: () living room () dining room (X) kitchen () bedroom (X) exterior (X) bathrooms () garage

NOTE: RECEPTACLES PRESENT IN BATHROOMS AND AT COUNTER TOPS IN KITCHENS MUST BE GROUND FAULT PROTECTED AND MUST BE INSTALLED ON SEPARATE 20 AMPERE CIRCUITS. EACH KITCHEN MUST HAVE CODE COMPLIANT COUNTERTOP GFCI PROTECTED RECEPTACLES AND EACH BATH MUST HAVE A GFCI PROTECTED RECEPTACLE. THIS WILL MOST LIKELY INCLUDE RUNNING A NEW CIRCUIT(S) TO THE BATHROOM AND TO THE KITCHEN

[INT. E9] () Provide electric lighting: () laundry area () furnace room () toilet room () utility room () kitchen () stairways
Note: Install 3-way switching to control lighting on stairways connecting one living space to another.

[INT. E10] (X) Install a separate wall mounted 20 ampere grounding type laundry circuit.

[INT. E11] (X) Install junction box for open spliced wiring in the following areas
APPLIES TO ANY OPEN JUNCTION BOXES THROUGHOUT THE PROPERTY

[INT. E12] (X) Change all ungrounded three (3) prong receptacles to two (2) prong polarized receptacles: _____

OTHER DEFICIENCIES:

(X) THE INTENT OF THE REPAIRS IS TO INSURE THAT ONCE THE UTILITIES ARE RESTORED TO THE PROPERTY ALL THE FIXTURES ARE FUNCTIONAL AND IN A SAFE/SOUND/SANITARY CONDITION.

(X) ALL LIGHT FIXTURES TO INCLUDE A GLOBE, NO BARE LIGHT BULBS

[ELECT. 1] (X) SECURE ELECTRICAL PERMIT FOR: RESUMPTION OF SERVICE AND ANY MODIFICATIONS MADE TO THE ELECTRIC SERVICE THROUGHOUT THE PROPERTY.

PRE - SALE INSPECTION REPORT

Location: 969 Manhattan Avenue Inspector: Sue Pratt Date: 6/24/2020

INTERIOR: PLUMBING

[INT. P]: PLUMBING

[INT. P1] (X) Remove obstruction and disinfect all contaminated surfaces: (X) sink (X) lavatory (X) bathtub () shower (X) water closet () laundry tub (X) floor drain (X) building drainage system.

[INT. P2] (X) Replace leaking: (X) sink trap (X) lavatory trap (X) bathtub trap () shower () laundry tub trap (X) waste piping (X) water piping () other _____

[INT. P3] (X) Replace faucets at: (X) sink () lavatory (X) bathtub (X) shower () laundry tub

[INT. P4] (X) Replace defective / missing: (X) sink () lavatory (X) bathtubs () shower () laundry tub (X) waste pipe NOTE THE CRACKED STACK IN BASEMENT PHOTOS. (X) water closets (X) water heater (X) water piping () other REPLACE THE BATHTUB IF IT DOESN'T CLEAN UP. REPLACE THE TOILET. REPLACE THE WATER HEATER COMPLETE TO COMPLY WITH THE C.O.D. BUILDING DEPARTMENT.

[INT. P5] (X) Replace missing: (X) cleanout plug(s) (X) floor drain cover(s).

[INT. P6] (X) Seal joint with approved material where fixture(s) contact wall and/ or floor: (X) sink (X) lavatory () bathtub (X) water closet () other _____

[INT. P7] (X) Provide tub-shower walls and partitions of a water resistant material.

[INT. P8] () Replace: () unapproved ballcock () defective flush mechanism, on water closet.

[INT. P9] () Reset loose: () water closet () lavatory () laundry tub () sink.

[INT.P10] () Repair worn surface: () bath tub () shower () sink () lavatory.

[INT. P11] (X) Provide proper water pressure (X) hot (X) cold, to: (X) sink (X) lavatory (X) water closet (X) bathtub (X) shower () laundry tub.

[W.H.]: WATER HEATER

[W.H. 1] () Correct back drafting of water heater.

[W.H. 2] () Install a 3/4 inch corrosion resistant unthreaded end discharge tube on water heater relief valve which shall terminate not more than four inches from floor.

[W.H. 3] () Install approved: () temperature - pressure relief safety valve () lever handle gas valve () drip leg on gas line.

[W.H. 4] () Seal opening around fume pipe where it enters chimney with non-combustible material.

[W.H. 5] () Replace defective fume pipe on water heater with approved material.

OTHER DEFICIENCIES:

(X) MAKE ALL NECESSARY REPAIRS SO THAT AT THE COMPLETION OF THE REHAB, THERE IS 1 FUNCTIONING BATH AND A FUNCTIONING KITCHEN. THE REMAINING BATH CAN BE COMPLETED AFTER THE DEED TRANSFER.

LBG. 1] () SECURE PLUMBING PERMIT FOR: MODIFICATIONS MADE TO THE PLUMBING SYSTEM. THE PLUMBING INSPECTIONS MUST BE COMPLETE AT THE TIME OF THE FINAL INSPECTION. THERE MUST BE AN OPERABLE WATER HEATER AT THE TIME OF THE FINAL INSPECTION. THE WATER HEATER MUST BE INSPECTED BY THE CITY OF DAYTON BUILDING DEPARTMENT PRIOR TO THE MCLB FINAL INSPECTION.

PRE - SALE INSPECTION REPORT

Location: 969 Manhattan Inspector: Sue Pratt Date: 6/24/2020

INTERIOR: HEATING

[INT. H]: HEATING

[INT. H1] () Repair or replace defective safety pilot: () furnace () boiler () space heater.

[INT. H2] () Correct the cause of delayed Ignition.

[INT. H3] () Adjust pilot flame and main burner for proper combustion.

[INT. H4] () Repair / replace defective: () limit control () pressure-trol () aqua-stat () low water cut off () thermostat.

[INT. H5] () Repair / replace defective manual main - shut off valve.

[INT. H6] () Repair or replace defective electrical shut - off switch.

[INT. H7] () Replace defective I missing vent connector and replace with approved material.

[INT. H8] () Correct back-drafting: () furnace () boiler.

[INT. H9] () Seal with non-combustible material the opening where vent connector enters chimney.

[INT. H10] () Provide a tight fitting and operable clean-out door at base of chimney.

[INT. H11] () Remove obstruction and I or debris from chimney.

[INT. H12] (X) Replace missing: () radiators (X) registers () furnace () boiler (X) hot /cold air ducts _____

[INT.H13] () Remove unapproved unvented space heating equipment and cap fuel lines.

[INT.H14] () Tests applied to this furnace reveal the presence of leaks from the furnace combustion chamber and/or flue passages _____ ppm detected. Repairs to the heat exchanger must be made by a certified welder and exposed for a visual examination by an Inspector from the Mechanical Inspection Division. Replacement of the heat exchanger or furnace requires that a permit be secured from the Mechanical Inspection Division.

OTHER DEFICIENCIES:

(X) EACH ROOM MUST HAVE A HEAT SOURCE. IT IS UP TO THE PURCHASER TO DECIDE WHAT TYPE OF HEAT SOURCE THEY WILL USE. IF THE EXISTING FURNACE IS USED PROVIDE THE LAND BANK WITH DOCUMENTATION SHOWING A LICENSED HVAC CONTRACTOR HAS INSPECTED THE FURNACE AND IT IS SAFE TO OPERATE. PROVIDE DOCUMENTATION OF A CLEAN AND TUNE. NOTE: GRAVITY FED REGISTERS ARE NOT ACCEPTABLE AS A HEAT SOURCE.

(X)

[MECH. 1] (X) SECURE MECHANICAL PERMIT FOR: WHATEVER TYPE OF PERMIT IS APPLICABLE FOR WHATEVER TYPE OF HEAT SOURCE CHOSEN



ADDITIONAL COSTS ASSOCIATED WITH THE PURCHASE OF A LAND BANK DIY PROPERTY

Per the *Montgomery County Land Reutilization Corporation DIY Renovation Sale and Purchase Agreement Notices* that you have initialed, item 10 states: *I understand that at the closing of my purchase of the property I will be required to reimburse the Land Bank for costs incurred to insure the property during the renovation period.* Please refer to page 6, item 6-f of the *Montgomery County Land Reutilization Corporation DIY Renovation Sale and Purchase Agreement* regarding the insurance the purchaser is required to maintain on the property.

PROPERTY ADDRESS 969 Manhattan

EFFECTIVE DATE: _____
(Date contract signed)

COMPLETION DATE: _____

Number of insurance days _____ @ a rate of \$1.45 per day = _____
TOTAL INSURANCE DUE

This is the current daily rate for the insurance the Land Bank has on this structure. It is possible the rate may change during your renovation period.

Please refer to page 6, item 6-f, of the *Montgomery County Land Reutilization Corporation DIY Renovation Sale and Purchase Agreement* regarding the builder's risk and general liability insurance the purchaser is required to maintain on the property during the renovation period.